



NOTES

1. SPECIAL CARE SHALL BE TAKEN WHEN FASTENING PLATES INTO THE STRUCTURAL DECK. OVER-DRIVING THE FASTENER WILL RESULT IN BUCKLING OR "CUPPING" OF THE PLATE AND WILL RESULT IN AN UNEVEN OR INADEQUATE BOND TO THE MEMBRANE. UNDER-DRIVING THE FASTENER WILL RESULT IN A LOOSE PLATE WITH INSUFFICIENT CLAMPING FORCE AND PROTRUDING FASTENER HEAD THAT MAY CAUSE DAMAGE TO THE MEMBRANE DURING WELDING OR NORMAL ROOF TRAFFIC.