



NOTES

1. CUT MOLDED TOP OFF AND CUT BOTTOM FLANGE WHERE MOLDED PRIOR TO TIGHTLY WRAPPING AND FLASHING PENETRATION. HOT-AIR WELD WRAPPED SEAM AND BOTTOM FLANGE TO MEMBRANE.



SHEET TITLE:
**PRE-MOLDED "WRAPID FLASH"
 PIPE PENETRATION FLASHING**

SCALE:
NTS

DRAWING No.:
DWG NO. 79