



NOTES

1. FOR HEAT-WELDING LAPS USE 1.5" MAX (25.4 mm) WELD WITH MACHINE AUTOMATIC WELDER AND 1.5" (127 mm) WELD WITH HAND WELDER.
2. APPLY TPO CUT EDGE SEALANT TO ALL CUT REINFORCED TPO EDGES