



NOTES

1. CONDUCTOR HEAD TO BE 1 INCH MINIMUM BELOW BOTTOM OF THROUGH-WALL SCUPPER.
2. PRIMING OF THE SUBSTRATE MAY BE REQUIRED, FOLLOW SPECIFICATIONS AND MANUFACTURER RECOMMENDATIONS.
3. REINFORCEMENT MUST BE FULLY SATURATED OR ENCAPSULATED IN BASE COAT AS DESCRIBED IN SPECIFICATIONS.



SHEET TITLE:
**BASE FLASHING AT
 THROUGH-WALL SCUPPER FULLY
 REINFORCED RESTORATION**

SCALE:
 NTS
 DRAWING No.:
DWG NO. LA-FR-25