



NOTES:

1. A FIELD WELD MUST NOT PASS UNDER THE CLAMPING RING
2. MEMBRANE MUST EXTEND MINIMUM 1" BEYOND THE BOLT HOLES
3. THE CLAMPING RING BOLT MUST PENETRATE THE MEMBRANE